

1. P100 Incremental Optical Encoder (Large Diameter Through Shaft)

1.1 Introduction:

P100 adopts a unique large-aperture through-shaft concentric locking device, a bearing-less ultra-thin design, multiple electrical interfaces, and no dust protection, which can solve the installation problem of large-aperture low space limitations.

1.2 Feature:

- Encoder external diameter $\varnothing 100\text{mm}$, thickness 12.8mm, diameter of shaft up to $\varnothing 63\text{mm}$;
- Adopt non-contact photoelectric principle;
- Reverse polarity protection;
- Short circuit protection;
- Multiple electrical interfaces available;
- Resolution per turn up to 10000PPR.

1.3 Application:

Servo motor, robot and automation control fields.

1.4 Connection:

- Radial socket (8P & 14P)
- Radial cable (standard length 1.0M)


1.5 Protection:

None


1.6 Weight:

About 150g


P100-E



P100-F




P100-J



2. Model Selection Guide

2.1 Model composition(select parameters)











2.2 Note

- Z signal is low level active.
- Z signal is high level active.
- None indicated for IP00 and cable length of 1.0M, if need to change the length C+number, the longest is 100M (expressed by C100). For the specific length of use, pls refer to page P2 -P3 of the provision of output circuit.

P100 INCREMENTAL

3. Output Mode

3.1 Incremental signal

Electrical interface	Output circuit	Output wave form
<p>OC NPN open collector circuit</p>		 <p>$a.b.c.d = \frac{T}{4} \pm \delta$</p> <p>Phase A is ahead of B by $\frac{T}{4} \pm \delta$, viewing from encoder front side, direction is counterclockwise rotation. (See dimensional drawings)</p> <p>CCW direction →</p> <p>Z signal is low level active</p>
<p>Voltage</p>		 <p>$a.b.c.d = \frac{T}{4} \pm \delta$</p> <p>Phase A is ahead of B by $\frac{T}{4} \pm \delta$, viewing from encoder front side, direction is counterclockwise rotation. (See dimensional drawings)</p> <p>CCW direction →</p> <p>Z signal is high level active</p>
<p>Push-pull</p>		 <p>$a.b.c.d = \frac{T}{4} \pm \delta$</p> <p>Phase A is ahead of B by $\frac{T}{4} \pm \delta$, viewing from encoder front side, direction is clockwise rotation. (See dimensional drawings)</p> <p>CW direction →</p>
<p>TTL (DC5V)</p> <p>HTL (DC8-30V)</p>		 <p>$a.b.c.d = \frac{T}{4} \pm \delta$</p> <p>Phase A is ahead of B by $\frac{T}{4} \pm \delta$, viewing from encoder front side, direction is clockwise rotation. (See dimensional drawings)</p> <p>CW direction →</p>

P100 INCREMENTAL Ver. 2.0 Page 3/11

3.2 For servo motor(with UVW)

Electrical interface	Output circuit	Output wave form																																																																	
<p>TTL (DC5V)</p>																																																																			
<p>TTL (DC5V) (Less wiring type)</p>	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>26LS31, 26C31 Transmission distance 200m Max</p> <p>Symbol signification</p> <ul style="list-style-type: none"> ★: indicate position of UVW channel ☆: position to start counting ABZ channel ▨: non-using zone HZ: high impedance </div> <div style="width: 50%;"> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th rowspan="2">No.</th> <th rowspan="2">Function Color</th> <th colspan="3">Mode</th> </tr> <tr> <th>1</th> <th>2</th> <th>3</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>white</td> <td>HZ</td> <td>U</td> <td>A</td> </tr> <tr> <td>2</td> <td>white/black</td> <td>HZ</td> <td>\bar{U}</td> <td>\bar{A}</td> </tr> <tr> <td>3</td> <td>green</td> <td>HZ</td> <td>V</td> <td>B</td> </tr> <tr> <td>4</td> <td>green/black</td> <td>HZ</td> <td>\bar{V}</td> <td>\bar{B}</td> </tr> <tr> <td>5</td> <td>yellow</td> <td>HZ</td> <td>W</td> <td>Z</td> </tr> <tr> <td>6</td> <td>yellow/black</td> <td>HZ</td> <td>\bar{W}</td> <td>\bar{Z}</td> </tr> <tr> <td>7</td> <td>red</td> <td colspan="3">DC+5V</td> </tr> <tr> <td>8</td> <td>black</td> <td colspan="3">OV</td> </tr> <tr> <td>0</td> <td>shielding</td> <td colspan="3">GND</td> </tr> </tbody> </table> </div> </div>	No.	Function Color	Mode			1	2	3	1	white	HZ	U	A	2	white/black	HZ	\bar{U}	\bar{A}	3	green	HZ	V	B	4	green/black	HZ	\bar{V}	\bar{B}	5	yellow	HZ	W	Z	6	yellow/black	HZ	\bar{W}	\bar{Z}	7	red	DC+5V			8	black	OV			0	shielding	GND			<p>Reverse signal not shown</p> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>pole</th> <th>g,h,j,k,m,n</th> <th>r</th> </tr> </thead> <tbody> <tr> <td>6</td> <td>$20 \pm 1^\circ$</td> <td>120°</td> </tr> <tr> <td>8</td> <td>$15 \pm 1^\circ$</td> <td>90°</td> </tr> <tr> <td>16</td> <td>$7.5 \pm 1^\circ$</td> <td>45°</td> </tr> </tbody> </table>	pole	g,h,j,k,m,n	r	6	$20 \pm 1^\circ$	120°	8	$15 \pm 1^\circ$	90°	16	$7.5 \pm 1^\circ$	45°
No.	Function Color			Mode																																																															
		1	2	3																																																															
1	white	HZ	U	A																																																															
2	white/black	HZ	\bar{U}	\bar{A}																																																															
3	green	HZ	V	B																																																															
4	green/black	HZ	\bar{V}	\bar{B}																																																															
5	yellow	HZ	W	Z																																																															
6	yellow/black	HZ	\bar{W}	\bar{Z}																																																															
7	red	DC+5V																																																																	
8	black	OV																																																																	
0	shielding	GND																																																																	
pole	g,h,j,k,m,n	r																																																																	
6	$20 \pm 1^\circ$	120°																																																																	
8	$15 \pm 1^\circ$	90°																																																																	
16	$7.5 \pm 1^\circ$	45°																																																																	
<p>Timing Chart</p>																																																																			
<p>a,b,c,d=$\frac{T}{4} \pm \frac{T}{8}$ e=$T \pm \frac{T}{2}$ f: center of phase Z to rise point of phase U, that is $\pm 1^\circ$ CW direction \rightarrow Viewed from encoder front side direction is clockwise rotation. (See dimensional drawings)</p>																																																																			

4. Electrical Parameters

Parameter / Item	Output type	OC	Voltage	Push-pull	TTL	TTL (Less wiring type)	HTL	
Supply voltage		DC+5V±5%; DC8V-30V±5%			DC+5V±5%		DC8-30V±5%	
Consumption current		100mA Max			120mA Max			
Allowable ripple		≤3%rms						
Top response frequency		100KHz			300KHz		500KHz	
Output capacity	Output current	Input	≤30mA	Load resistance 2.2K	≤30mA	≤±20mA	≤±50mA	
		Output	—		≤10mA			
	Output voltage	"H"	—	—	≥ [(Supply voltage) -2.5V]	≥2.5V	≥Vcc-3 Vbc	
		"L"	≤0.4V	≤0.7V(less than 20mA)	≤0.4V(30mA)	≤0.5V	≤ 1V Vbc	
Load voltage		≤DC30V	—		—			
Rise & Fall time		Less than 2us(cable length: 2m)			Less than 1us(Cable length: 2m)			
Insulation strength		AC500V 60s						
Insulation resistance		10MΩ						
Mark to space ratio		45% to 55%						
Reverse polarity protection		✓						
Short-circuit protection		—			✓①			
Phase shift between A & B		90°±10° (frequency in low speed)						
		90°±20° (frequency in high speed)						
Delay motion time ②		—				510±220ms	—	
GND		Not connect to encoder						

- ① Short-circuit to another channel or GND permitted for max.30s.
- ② Phase A.B.Z are back of phase U.V.W when power on.

5. Mechanical Specifications

Diameter of shaft	Ø40mm; Ø63mm(optional)
Slew speed	≤6000 rpm
Material	Base: Die cast aluminum
Weight	About 150g

6. Environmental Parameters





Environmental temperature	Operating: -20~+85°C(repeatable winding cable: -10°C); Storage: -20~+90°C
Environmental humidity	Operating and storage: 35~85%RH(noncondensing)
Vibration(Endurance)	Amplitude 0.75mm,5~55Hz,2h for X,Y,Z direction individually
Shock(Endurance)	940m/s ² 11ms three times for X,Y,Z direction individually
Protection	None

7. Wiring Table

7.1 OC / Voltage








Socket pin No.	Incremental signal						Supply voltage	
	1	2	3	4	5	6	7	8
Wire color	White	-	Green	-	Yellow	-	Red	Black
Function	A	-	B	-	Z	-	Up	0V

7.2 TTL / HTL / Push-pull / Less wiring type

Socket pin No.	Incremental signal						Supply voltage	
	1	2	3	4	5	6	7	8
Wire color	White	White/BK	Green	Green/BK	Yellow	Yellow/BK	Red	Black
Function	A+ (U+)*	A- (U-)*	B+ (V+)*	B- (V-)*	Z+ (W+)*	Z- (W-)*	Up	0V
Twisted-paired cable								

* For the functional status in less wiring mode, refer to the functional mode wiring table for output circuit on page3.

7.3 For servo motor


Socket pin No.	Incremental signal												Supply voltage	
	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Wire color	Grey	Grey/Bk	Blue/Bk	Blue	Pink/Bk	Pink	Yellow	Yellow/BK	Green	Green/BK	White	White/BK	Black	Red
Function	V+	V-	U-	U+	W-	W+	Z+	Z-	B+	B-	A+	A-	0V	Up
Twisted-paired cable														

Up=Supply voltage.


Shield wire is not connected to the internal circuit of encoder.

8. Socket & Cable

8.1 Socket pin definition




8.2 Radial Cable Schematic




Unit: mm

9. Basic Dimension


9.1 P100-E




9.2 P100-F




9.3 P100-J



9.4 Installation shaft specification



Unit: mm



↻ = Shaft rotation direction of TTL & HTL signal output
 ↻ = Shaft rotation direction of OC signal output

R1 = Radial socket 8P (SM08B-GHS-TB).
 R2 = Radial socket 14P (SM14B-GHS-TB).
 R3 = Radial cable (standard length 1M).


10. Assembly Steps for Servo Motor Encoder

10.1 Encoder installation and zero position alignment with U.V.W

Step 1

- a. Before installing the encoder, first confirm the motor's starting zero position and lock it to ensure that the motor shaft remains stationary until the encoder is installed. Otherwise, the encoder zero position and the motor zero position cannot be aligned.
- b. Put the encoder (2) directly on the motor shaft and gently push it onto the motor platform by hand.
- c. Tighten the three M3*12 bolts (3) at the same time, but do not tighten them. Just enough to rotate the encoder by hand.


Note: For the matching tolerance of the encoder sleeve and motor shaft, please refer to P7.



Step 2

- a. Clamp the wrench (A) onto the shaft sleeve, then clamp the wrench (B) onto the lock nut and tighten (make sure the encoder is in close contact with the motor platform when tightening).
- b. Connect according to the selected socket wiring table on P5 of this specification, check and power on, and observe that the LED on the encoder PCB is on when the zero position signal is aligned. In this state, tighten the three M3*12 bolts (3), then remove the bolts (4) (5) and remove the positioning plate (6). The encoder can be used.


If the LED is not on, please continue from step 3.



Step 3

- a. Remove the three M2*6(4) first
- b. Refer to the socket wiring table selected on P5 of this specification for connection, check and power on. Please confirm again that the motor is in the zero position locked state, then turn the encoder left and tight by hand (2), and observe that the LED on the encoder PCB is on when the zero position signal is aligned. Then tighten the three M3*12 bolts (3) and keep the LED on.


Note: Because the zero position signal width is relatively narrow, it is easy to cause displacement during the tightening process, making the LED not light up. Please debug patiently or use other visual equipment as an auxiliary observation.



Step 4

- a. Remove the three M2*5 bolts (5) and discard them.
- b. Remove the assembly positioning plate (6) and the encoder can be used.

Note: If you need to re-zero or disassemble the encoder (2), you must reinstall the assembly positioning plate (6).




10.2 Incremental encoder installation steps

Step 1

- a. Put the encoder (2) directly on the motor shaft and gently push it to the motor platform by hand.
- b. Screw on the three M3*12 bolts (3) at the same time, but do not tighten them tightly. Just enough to rotate the encoder by hand.


Note: For the matching tolerance of the encoder sleeve and the motor shaft, please refer to P7.



Step 2

- a. Clamp the wrench (A) onto the shaft sleeve, then clamp the wrench (B) onto the lock nut and tighten it (make sure the encoder is in close contact with the motor platform when tightening), then tighten the three M3*12 bolts (3), remove the six (4) (5) bolts, and remove the positioning plate (6).
- b. Refer to the selected socket wiring table on P5 of this specification for connection. After checking that everything is correct and powering on, the encoder can be used.

Note: If you want to remove the encoder (2) or reinstall it, you must reinstall the assembly positioning plate (6).



11. Caution

11.1 Caution for use

- Ambient temperature must not exceed the storage temperature.
- Relative humidity must not exceed the storage humidity.
- Not in a place with rapid temperature changes or fogging.
- Close to corrosive gases and flammable gases.
- Away from places with a lot of dust, salt, and metal powder.
- Away from places where water, oil and chemicals are used.
- Where excessive vibration and impact will be transmitted to the body.

11.2 About vibration

Vibration act on encoder always cause wrong pulse, so we should pay attention to working place. More pulse per revolution, narrower groovy spacing of grating, more effect to encoder by vibration, when rev is low or stop, vibration act on shaft or main body would cause grating vibrating, so encoder might make wrong pulse.

11.3 Caution for wiring

- Use the encoder under the specified supply voltage. Please note that the supply voltage range may drop due to the wiring length.
- Do not put the encoder wiring and other power lines through the same duct, and do not use them by bundling in parallel.
- Please do not apply excessive force to the cable of encoder, or it will may be damaged.